



optibelt TB

TAPER BUSHES

DIMENSIONS	
TAPER BUSHES	BORE DIAMETERS
1008	10–25 mm
1108	10–28 mm
1210	11–32 mm
1215	11–32 mm
1310	14–35 mm
1610	14–42 mm
1615	14–42 mm
2012	14–50 mm
2517	16–60 mm
3020	25–75 mm
3030	35–75 mm
3525	35–90 mm
3535	35–90 mm
4040	40–100 mm
4545	55–110 mm
5050	70–125 mm



optibelt CE

BASE ELEMENT

DIMENSIONS	
DESIGNATION	BORE DIAMETERS
CE01	18–400 mm
CE02	6–100 mm
CE03	6–150 mm
CE04	20–180 mm
CE05	20–200 mm
CE06	20–180 mm
CE07	20–200 mm
CE08	25–200 mm
CE09	45–100 mm
CE10	14–60 mm
CE11	14–60 mm
CE12	16–60 mm
CE13	15–70 mm
CE14	24–260 mm